

Northridge Paver Replacement

The Northridge Community contains 9 intersections composed of concrete brick pavers with concrete borders. These intersections have deteriorated over time to the point they require replacement. Assessments were performed rating conditions, utilizing these assessments a replacement program was developed to restore these intersections to occur over a 6 year period.

